



Tech Bulletin

To: Tommy Gate Distributors
From: Tommy Gate Company
Date: March 24, 2008
Re: 2007 – Present Sprinter Van Step Bumper Incompatible with Model 650

2007 – Present Sprinter Van Step Bumper Incompatible with Model 650

The 2007 – Present Sprinter Van may be equipped with a rear step bumper. **This rear step bumper is not compatible with a Model 650 lift gate.** The bumper consists of two corners and a center section. The center section of **the bumper can be unbolted and replaced with a standard bumper.**

With the standard rear bumper installed, the Model 650 can be installed successfully in both the standard and high roof 2007-present Sprinter Vans.