


| ITEM NO. | QTY. | PART NO. | DESCRIPTION                                 |
|----------|------|----------|---|
| 1        | 1    | 008091   | 335 PITCH ROLLER CHAIN(AB)DRIVER'S SIDE(95) |
| 2        | 1    | 007661   | 50 SERIES CONNECTING LINK                   |
| 3        | 2    | 000552   | 5/8-18 SAE HEX FIN NUT                      |
| 4        | 1    | 007667   | 5/8"x5-3/4" CHAIN ADJUSTMENT BOLT           |
| 5        | 1    | 007666   | 1.12"DIA.x1.5" RAIL CHAIN TENSIONER         |
| 6        | 2    | 009967   | 1/16"x1/2" COTTER PIN                       |
| 7        | 1    | 009867   | 0.200x1.344" HEAT CHAIN CLEVIS PIN          |
| 8        | 1    | 095041   | ROLLER CHAIN REPLACEMENT GUIDE              |



| REV. | DATE     | CHANGE RECORD                          | BY  | APPVD | ECN  | THIRD ANGLE PROJECTION          |                |                | FILENAME:                 |              | WOODBINE MFG. CO.<br>BUS BROWN DRIVE<br>WOODBINE, IOWA 51579   |   |
|------|----------|--|-----|-------|------|---------------------------------|----------------|----------------|---------------------------|--------------|--|---|
|      |          |  |     |       |      | DECIMAL                         | 2PLC           | 3PLC           | SYMBOLY PER<br>ANSI Y14.5 | NOTES:       | 712-647-2050   |   |
| C    | 2/19/14  | REMOVED (1) 7317                       | JCB |       | 1056 | MACHINE<br>SAW,DRILL            | .030           | .015           | DRAWN BY:<br>DJR          |              |  |   |
| B    | 3/30/09  | REPLACED PN 7947 WITH INDIVIDUAL PARTS | JCB | JCB   | 121  | SHEAR,<br>PUNCH<br>FORM         | .060           | .030           | DRAWN/DATE<br>10/3/03     |              |  | THE INFORMATION HERE IS CONFIDENTIAL<br>AND MUST NOT BE USED IN ANYWAY<br>DETRIMENTAL TO THE INTEREST OF<br>WOODBINE MFG. |
| A    | 12/22/08 | ADDED PN 95041                         | JCB | JCB   | 91   | TORCH,<br>WELDING<br>ROUGH CAST | .090           | .060           | APPVD/DATE                | TITLE        | 335 PITCH REPLACEMENT ROLLER CHAIN ABOVE BED DRIVER'S SIDE(95) |   |
|      |          |  |     |       |      | DRAFT<br>2°                     | ANGULAR<br>±1° | SALES CATEGORY | PRODUCT LINE              | SCALE<br>1:4 | FIN. WT.   | PART NO.<br>8044  |